Here are the pictures of the cap during the 2/24/16 visual inspection - the exposed geotextile locations are shown on an aerial of the site.

Gary Miller
Remedial Project Manager
EPA Region 6 – Superfund Division (6SF-RA)
214-665-8318
miller.garyg@epa.gov

From: Walters, Donn
Sent: Wednesday, March 09, 2016 3:54 PM
To: Allen, Bob (PCS) <Bob.Allen@pcs.hctx.net>; lhenry@poha.com; Leah Oberlin <loberlin@poha.com>; satya.dwivedula@tceq.texas.gov; Crystal Taylor <crystal.taylor@tceq.texas.gov>; Walker,Tina (DSHS) <Tina.Walker@dshs.state.tx.us>; Ellerbee,Tom (DSHS) <Tom.Ellerbee@dshs.state.tx.us>; Darbonne, Jacque (Commissioner Precinct 2) <Jacque.Darbonne@pct2.hctx.net>; Owens, Rock (CAO) <Rock.Owens@cao.hctx.net>; Jacquelyn Young <jeyoung@texanstogether.org>; sjones@galvbay.org; Mary Jane Naquin <M.J.Naquin@InformedFutures.com>; Moreira, Dave <Dmoreira@wm.com>; Philip J Slowiak <Philip.Slowiak@ipaper.com>
Cc: Miller, Garyg <Miller.Garyg@epa.gov>; Sanchez, Carlos <sanchez.carlos@epa.gov>; McCorkhill, Michael <Mccorkhill.Michael@epa.gov>; Talton, Anthony <Talton.Anthony@epa.gov>
Subject: CAC notification; San Jacinto Waste Pits Superfund Site Update

This notice is in regard to a current site event:

"The PRPs are scheduled to conduct the assessment and repair beginning on March 9, 2016, with completion on March 11, 2016, weather and tide permitting.   The Potentially Responsible Parties conducted a visual inspection of the cap on February 24 and found a couple of areas where geotextile fabric did not have armored rock cover. The PRPs notified EPA on March 4 and we directed them to place additional rock over these areas and approved a plan to conduct this work under EPA oversight."

Local Congressional have been updated.

Thanks,

9769060